

Report ID:	27,163,742	Version:	4
Created:	10 Nov 2025		

T		Daa:	Report ID: 27,163,742		Ve	rsion:	4		
Turners Ba			c Condition Guide	Created:	10 Nov 2025				
Make:	KIA	Model:	Sportage			ОК	Requi Attent		N/A
Body Style:	SUV	Year:	2006	Engine					
Rego No.:	DZL498	Rego Expiry:	01 Mar 2026	Oil level		/			
WoF Expiry:	16 Apr 2026	Odometer:	184,812 Kms	Smoke & fu	ımes	1	-		
Good No.:	27163742	VIN:	KNEJE55186K183311	Engine per	formance	1			
Next Service:	193000 Kms	Service History:	No	Noise		1			
Note: This report is	•			Coolant co	ndition	1			
diagnostic testing ur	ndertaken. The vehicle ha b	een driven up to 50km/	Parts have not been dismantled or 'h from cold. The Vendor recommends a	Cooling pe	rformance	1			
full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Hoses (visual)	1			
Key S = Scratch R	– Rust	rack *= Deca	ls W = Significant scuffs	Transmiss	ion				
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffsD = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation		/			
D PT SP				Noise		1			
				Clutch					V
				CV joints		1			
			S	Wheel bea	rings	1			
SSC				Brakes					
	M 11 >			Performan	ce	/			
				Hand brake	 e	1			
SC	R			Tyres (lowest observed tread depth of tyres)					
				Left front		5.9 mr			
			PT P	Right front		6.0 mm			
				Left rear		3.2 mi			
S PT S P P				Right rear		2.6 n			.6 mn
Note: some defects and blemishes may not be displayed in the diagram				Spare		Yes			
Body Inspection	on Comments			Suspensio	n				
Windscreen ch	ips. Drivers Seat base	e side bolster rippe	d. Rear Seat headrests missing.	Suspension	n performance	/			
				Steering pe	erformance	1			
				Shock abso	orbers	1			
Conditions Dur	ring Body Inspection		Dry	Air Condit	ioning / Heater	,			
Under Carriage and Under Bonnet Inspection Comments			Operation		/				
Oil leaks.				Electrical /	Accessories				
				Head light:	5	'			
				Tail lights		1			
Interior Comm	Interior Comments			Indicators		1	İ		

Oil leaks.	
Interior Comments	

Interior Comments			
	Seats:	Poor	
	Carpets:	Average	
	Panels:	Average	
	Dashboard:	Average	
	Company		

Sway bay knock - Left front window not going up from door.

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Chris McQuade			
Published by:	Jason Bucksey			
Inspection Date:	03 Nov 2025			

		5.9	ШП
Right front		6.0	mm
Left rear		3.2	mm
Right rear		2.6	mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	V		
Tail lights	V V V		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	/		
Window winder FL	V		
Window winder FR	/		
Window winder RL	V		
Window winder RR	V V		
Rear view mirrors	/		
Radio (basic test only)	V		
CD (basic test only)	/		
Number of keys	1		
Central locking	/		
Remote locking			/
Sat. nav. (basic test only)			/
			/

I have read and understood this condition guide:

NAME