

Basic Condition Guide


•	Report ID:	27,183,318	Version:	2
	Created:	18 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise		V	
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	'		
Noise	/		
Clutch			1
CV joints	V		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	
Left front		(3.0 mr
Right front			1.0 mr
Left rear			2.5 mr
Right rear		(6.0 mr
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1	<u> </u>	
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
	1		
Radio (basic test only)	+ -		-
Radio (basic test only) CD (basic test only)			
CD (basic test only)	1		
CD (basic test only) Number of keys	1	1	
CD (basic test only) Number of keys Central locking	1		
CD (basic test only) Number of keys	/		<i>\</i>

Make:	Honda	Model:	Insight
Body Style:	Hatchback	Year:	2012
Rego No.:	NRB780	Rego Expiry:	09 Jul 2026
WoF Expiry:	29 Aug 2026	Odometer:	128,479 Kms
Good No.:	27183318	VIN:	7AT08G9MX21005144
Next Service:	138,000	Service History:	No
Note: This report is r	not a warranty		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Tailgate Small Rust Spot

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Rust on Sill Pinch Welds.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
	_	

General Comments

Minor Engine Tick - Common Reversing Camera Intermittent Fault

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Darren Beban	
Published by:	James Scott	
Inspection Date:	13 Nov 2025	

I have read and understood
this condition guide:

NAME			