

Report ID: 27,787,205		Version:	1
Created:	03 Dec 2025		

U	nuer	S Basi	c Condition Guide			
Make:	Honda	Model:	Stream			
Body Style:	Wagon	Year:	2009			
Rego No.: MZW721		Rego Expiry:	29 Jan 2026			
WoF Expiry: 25 Aug 2026		Odometer:	116,545 Kms			
Good No.:	27787205	VIN:	7AT08GADX20103116			
Next Service:	126500	Service History:	No			
diagnostic testing und	only. Consideration is made dertaken. The vehicle has b	een driven up to 50km/h	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.			
Key  S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips  W  S SC W  S SC S  S SC S  S W						
Body Inspection	on Comments	displayed in the diagra				
•						
Conditions Duri	ng Body Inspection		Dry			
Under Carriage and Under Bonnet Inspection Comments						
Interior Comm	ents					
Seats:	Average					
Carpets:	Average					
Panels:	Average					
. direis.	, o. ugo					

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	<b>/</b>		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	V		
Radiator / Hoses (visual)	/		
Transmission			
Operation	<b>/</b>		
Noise	1		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			I
Performance	V	Ι	1
Hand brake	<b>/</b>		
Tyres (lowest observed tread	depth of	tvres)	
Left front			7.0 mr
Right front			7.0 mr
Left rear			7.0 mr
Right rear		-	7.0 mr
Spare	Yes		.0 1111
Suspension	100		
Suspension performance	1		Π
Steering performance	V		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		l
Electrical / Accessories			
		Ī	
Head lights	V		
Tail lights	_		
Indicators	<i>V</i>	-	
Dashboard warning lights	1		
Wipers (front & rear)	<i>V</i>		
Window winder FL	V	-	
Window winder FR	V		
Window winder RL	<b>/</b>		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	1	1	
Central locking	/		
Remote locking	/	ļ	
Sat. nav. (basic test only)			
Reversing camera	V		

Stations.					
Road Conditions During Test Drive		Dry			
Engine Timing Mechanism		Timing Cha	in		
Evidence of Cam Belt Replacement		Yes	No	Kms	
Inspected by:	Finlay Lemmens				

Left wing mirror fold function inoperative. Radio requires band expander to get all  $\ensuremath{\mathsf{NZ}}$ 

I have read and understood	k
this condition quide	

Published by: Luke Saunders Inspection Date: 18 Nov 2025

Dashboard:

**General Comments** 

Average

NAME			

SIGNATURE		