

•	Report ID: 27,791,480		Version:	1	
	Created:	19 Nov 2025			

CA T	11000	Rasi	c Condition Guide	Report ID: 27,791,480	ve	rsion: 1		
	nue			Created: 19 Nov 2025				
Make:	Holden	Model:	Captiva 7			Requires		
Body Style:	SUV	Year:	2018	Engine	OK	Attention	N/A	
Rego No.:	QWU928	Rego Expiry:	19 Feb 2026	Oil level	V			
WoF Expiry:	26 Nov 2026	Odometer:	74,825 Kms	Smoke & fumes	1			
Good No.:	27791480	VIN:	KL3CD2659JB023728	Engine performance	1			
Next Service:	88,000	Service History:	No	Noise	1			
Note: This report	is not a warranty		·	Coolant condition	1			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommendation of the vehicle has been driven up to 50km/h from cold.				Cooling performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
full mechanical ins	spection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)	1			
Key				Transmission				
S = Scratch $R = Rust$ $C = Crack$ *= Decals $W = Significant scuffs$ $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$				Operation	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<u> </u>		
	TT=Tallit defect T=T		nic Criips	Noise	Ť	V		
s		s s	S	Clutch				
				CV joints	· /			
	$\mathcal{O}_{\mathcal{C}}$		SPW	Wheel bearings	1			
SPT				Brakes				
Alderson				Performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
			SD	Hand brake	1			
s sc	HO			Tyres (lowest observed tread depth of tyres)				
S SP S				Left front 5.0 mm				
				Right front	5.0 mm			
				Left rear	5.5 mm			
				Right rear	2.5 mm			
Note: some defect	ts and blemishes may not be	displayed in the diagra	am .	Spare	Yes			
	tion Comments	displayed III the diagra		Suspension				
Stone chips in				Suspension performance	V			
				Steering performance	1			
				Shock absorbers	1			
Conditions D	uring Body Inspection		Dry	Air Conditioning / Heater				
	age and Under Bonnet	Inspection Comm		Operation	V			
Power steering	g seepage	<u> </u>		Electrical / Accessories				
Driveshaft cen	ntre bearing bracket ber	nt		Head lights	V			
				Tail lights	1			
Interior Com	nments			Indicators	·			
Seats:	Average			Dashboard warning lights	1			
Carpets:	Average			Wipers (front & rear)	1			
Panels:				Window winder FL	1			
Dashboard: Average				Window winder FR	1			
General Comments				Window winder RL	1			
Transmission whine. Humming noise at speed Strong smell inside				Window winder RR	1			
				Rear view mirrors	1			
				Radio (basic test only)	1			
		1_		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_			

	Road Conditions During Test Drive		Dry
	Engine Timing N	Mechanism	Timing Chain
	Evidence of Cam Belt Replacement		Yes No Kms
	Inspected by:	Samuel Weir	
ĺ	Published by:	Brandon Willmore	•
	Inspection Date:	17 Nov 2025	

I have read and understood
this condition auide:

NAME			

2

1

•

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking