

•	Report ID: 27,799,033		Version:	1
	Created:	04 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	/		
Engine performance	✓ ✓		
Noise	V		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	V		
Transmission		1	
Operation	✓		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tvres)	
Left front			6.0 mm
Right front			6.0 mm
Left rear			5.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	1		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/	1	
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	1		
Central locking	/	1	
Remote locking			
Sat. nav. (basic test only)			
Reversing camera			


Make:	Toyota	Model:	Rav4
Body Style:	suv	Year:	2006
Rego No.:	DHC995	Rego Expiry:	14 Jun 2026
WoF Expiry:	23 Dec 2025	Odometer:	224,413 Kms
Good No.:	27799033	VIN:	JTMBD31V905019402
Next Service:	224000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Aerial mast missing,

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Oil seepage lower engine Area,

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good
General Comments	

Service Due, Slight noise in steering column at low speed .

Road Condition	s During Test Drive	Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Chris Buckley		
Published by:	Jeremy Hutchings	S	
Inspection Date:	20 Nov 2025		

have read and understood
this condition quide

NAME			