

•	Report ID:	27,831,767	Version:	1
	Created:	04 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	1		
Noise	~		
Coolant condition	1		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	~		
Brakes			
Performance	~		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		5	5.5 mm
Right front		5	5.5 mm
Left rear		6	3.0 mm
Right rear		6	3.0 mm
Spare	N/A		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	•		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	•		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	•		
Number of keys	1	1	
Central locking	•		
Remote locking	~		
Sat. nav. (basic test only)			_
Reversing camera			

Make:	BMW	Model:	1201
Body Style:	Hatchback	Year:	2009
Rego No.:	NJN242	Rego Expiry:	15 Mar 2026
WoF Expiry:	20 Aug 2026	Odometer:	88,881 Kms
Good No.:	27831767	VIN:	WBAUD32060P220834
Next Service:	98000	Service History:	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

No flat tyre kit

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

2wd/major engine oil leak further investigation needed/

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Burning oil smell after test drive/ intermittent hard shift gearbox service needed/

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Uriah Pepene	
Published by:	Harry Clark	
Inspection Date:	03 Dec 2025	

have read and understood
this condition quide

NAME			