

## **Basic Condition Guide**


_				
	Report ID:	27,832,738	Version:	1
	Created:	11 Dec 2025		

	OK	Requires Attention	N/A
Engine	<u> </u>	7100011011	
Oil level	V		
Smoke & fumes	V		
Engine performance	V		
Noise	V		
Coolant condition	V		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission			
Operation	V		
Noise			
Clutch			1
CV joints	V		
Wheel bearings	V		
Brakes			
Performance	V		
Hand brake	V		
Tyres (lowest observed tr	ead depth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear			6 mm
Right rear			6 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heate	er		
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	V		
Indicators	V		
Dashboard warning lights			
Wipers (front & rear)	V		
Window winder FL	V		
Window winder FR	V		
Window winder RL	V		
Window winder RR	V		
Rear view mirrors	V		
Radio (basic test only)	V		
CD (basic test only)			
Number of keys	2		l
Central locking	V		
Remote locking	/		
Sat. nav. (basic test only)			V
Reversing camera			1
3			

			Γ	
Make:	Subaru	Model:	Legacy	
Body Style:	Wagon	Year:	2012	
Rego No.:	MHL592	Rego Expiry:	01 Dec 2025	
WoF Expiry:	26 Jun 2026	Odometer:	180,743 Kms	
Good No.:	27832738	VIN:	7AT0GF0BX19007028	
Next Service:	185,400 kms	Service History:	No	
Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				

$\mathbf{v}$	~~.
n	eν

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Windscreen stone chip cracked

FL power window control driver side not working

FL power window control passenger side jamming

FL seat position adjust knob missing

		•	•	
Co	nditions Duri	ng Body Inspectio	n	Dry

## **Under Carriage and Under Bonnet Inspection Comments**

AWD

**Interior Comments** 

Seats:	Good			
Carpets:	Good	Good		
Panels:	Good	Good		
Dashboard:	Good	Good		
General Comn	General Comments			
Headlights faded FR headlight washer cover panel missing Front and Rear bumper refit Front fog lamps not glowing				
		Timing Chain		
Engine Timing Mechanism  Evidence of Cam Belt Replacement		Yes No Kms		
Inspected by: Vasanthakumar M				
Published by:	Vasanthakumar Mayilswamy			
Inspection Date:	11 Dec 2025			

I have	read	and	understood
thic co	nditi	on a	uido

NAME	