

Report ID: 27,850,4		27,850,400	Version:	3
	Created:	10 Dec 2025		


	ОК	Requires Attention	N/A
Engine	- Oit	Accention	14//1
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V	<u> </u>	
Noise	1		
Clutch	-		-1
CV joints	-		
Wheel bearings		l	
Brakes		ı	
Performance	/		
Hand brake	/		
Tyres (lowest observed tread	depth of	tyres)	
Left front			5 mn
Right front			5 mn
Left rear			2 mn
Right rear			2 mn
Spare	Yes		
Suspension	_		
Suspension performance	/		
Steering performance	/		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories		<u> </u>	
Head lights	V		
Tail lights	1		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	1	1	
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1	1	
Rear view mirrors	1		
Radio (basic test only)			
CD (basic test only)		<i>-</i>	
Number of keys	1		L
Central locking	1		
	1	-	
Remote locking		-	.,
Sat. nav. (basic test only)			.,
Reversing camera		ļ	

Make:	Subaru	Model:	Legacy
Body Style:	Sedan	Year:	2007
Rego No.:	LYF514	Rego Expiry:	22 Oct 2026
WoF Expiry:	23 Oct 2026	Odometer:	205,429 Kms
Good No.:	27850400	VIN:	7AT0GF0BX18078425
Next Service:	207,652kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

\mathbf{v}	~~.
n	eν

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Bonnet edges bent.

Chipped windscreen.

Left wing mirror casing & indicator lens broken.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Left inner CV boot split.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard: Dashboard & vents damaged, S/wheel worn.		

General Comments

Noises in pulley / belt area, possibly alternator & power steering. Radio, CD & centre screen not working.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Daryll Timms			
Published by:	Daryll Timms			
Inspection Date:	10 Dec 2025			

I have read and understood
this condition guide:

NAME		