


•	Report ID:	27,853,187	Version:	1
	Created:	16 Dec 2025		

Engine Oil level Smoke & fumes Engine performance Noise Coolant condition	
Oil level Smoke & fumes Engine performance Noise	
Engine performance Noise	
Noise 🗸	
Noise 🗸	
Coolant condition	
Cooling performance	
Radiator / Hoses (visual)	
Transmission	
Operation 🗸	
Noise 🗸	
Clutch	✓
CV joints 🗸	
Wheel bearings	
Brakes	
Performance 🗸	
Hand brake	
Tyres (lowest observed tread depth of tyres)	
Left front	7 mm
Right front	7 mm
Left rear 9	9 mm
Right rear	9 mm
Spare Yes	
Suspension	
Suspension performance	
Steering performance	
Shock absorbers 🗸	
Air Conditioning / Heater	
Operation 🗸	
Electrical / Accessories	
Head lights 🗸	
Tail lights	
Indicators 🗸	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL 🗸	
Window winder FR	
Window winder RL	•
Window winder RR	~
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Number of keys 1	
Central locking	
Remote locking 🗸	
Sat. nav. (basic test only)	/
Reversing camera 🗸	

4	nue	rs _	Basi	c Cond	dition Guide		
Make:	Volkswagen	Model:		T6			
Body Style:	Van	Year:	Year: 2018				
Rego No.:	LLU499	Rego Ex	piry:	24 Mar 2026			
WoF Expiry:	25 Aug 2026	Odomet	Odometer:		247,855 Kms		
Good No.:	27853187	VIN:	VIN:		WV1ZZZ7HZJX029351		
Next Service:		Service	Service History:		No		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							
Key		'					
S = Scratch R =	= Rust C =	= Crack	* = Decal	S	W = Significant scuffs		
D = Dent PT	= Paint defect P =	Pin dent	SC = Stor	ne Chips			
		SDP	S P				



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Windscreen stone chip Broken high stop light

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Interior Comm	nents	
Seats:	Poor	
Carpets:	Poor	
Panels:	Poor	
Dashboard:	Poor	
General Comments		

Road Conditions During Test Drive		Wet		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	✓ No	Kms
Inspected by:	Kilipati Mae			
Published by:	Kilipati Mae			
Inspection Date:	16 Dec 2025			

I have read and understood	k
this condition quide	

NAME			

IG	NΔ	TU	RE	