

•	Report ID:	27,854,757	Version:	1
	Created:	12 Dec 2025		

AT.			in Condition Cuide	Report ID: 27,854,757	Ve	rsion: 1	
	urner	S Basi	c Condition Guide	Created: 12 Dec 2025	5		
Make:	Honda	Model:	Accord			Requires	
	Sedan		2001		ОК	Attention	N/A
Body Style:		Year:		Engine			
Rego No.:	AEJ220	Rego Expiry:	30 Aug 2026	Oil level	/		
WoF Expiry:	17 May 2026	Odometer:	195,346 Kms	Smoke & fumes	/		
Good No.:	27854757	VIN:	MRHCG56401P030128	Engine performance	/		
Next Service:	202500	Service History:	Yes	Noise	✓		
Note: This report is	•	e for age and mileage Pa	arts have not been dismantled or	Coolant condition	V		
diagnostic testing ur		een driven up to 50km/l	h from cold. The Vendor recommends a	Cooling performance	V		
	- Control to parenase an	- Install be all all ged i	or arradational charge.	Radiator / Hoses (visual)	V		
Key S = Scratch R	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmission			
	$\Gamma = Paint defect P = Pi$		•	Operation	V		
		7.00		Noise	/		
s sc	W	P SC P SC	WP	Clutch			~
			D DT W	CV joints			
			D PT W	Wheel bearings			
SC W				Brakes			
M	19 11			Performance	· /		
		—	PT	Hand brake			
S R SC	10			Tyres (lowest observed tread depth of tyres)			
01/00				Left front	du deptir or		4 mm
			S	Right front			4 mm
		Left rear			2 mm		
S D SC	W PT	Right rear		-	2 mm		
				Spare	Yes		
	and blemishes may not be	displayed in the diagra	am	Suspension			
Body Inspecti	ills have paint fade					l	
Rear bumper m	•			Suspension performance	- 1		
Right wing mirror cracked				Steering performance	-		
			1_	Shock absorbers			
Conditions During Body Inspection Dry				Air Conditioning / Heate		I	
Under Carriage and Under Bonnet Inspection Comments				Operation	/		
Underbody surf	ace rust			Electrical / Accessories		ı	
				Head lights			
				Tail lights	/		
Interior Comments			Indicators				
Seats:	worn seats			Dashboard warning lights	/		
Carpets:	Average			Wipers (front & rear)			
Panels:	Average			Window winder FL	V		
Dashboard: Average			Window winder FR	· /			
General Comr	General Comments				·		
							$\overline{}$

Carpets:	Average				
Panels:	Average				
Dashboard:	Average				
General Comm	General Comments				
Both remote key buttons are missing Partial service history					
Noisy steering pump, requires further investigation					
D 16 1111	0 : 1 : 0 : D				

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	153,712 Kms
Inspected by:	Sione Mae			
Published by:	Sione Mae			
Inspection Date:	12 Dec 2025			

I have read and underst	ood
this condition guide:	

NAME		

SIGNATURE			

1

1 3

1

1

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking