

Basic Condition Guida

•	Report ID:	27,855,696	Version:	1
	Created:	15 Dec 2025		

U	nuer	S Basi	c Condition Guide	Created:	15 Dec 2025			
Make:	Toyota	Model:	Altezza			ОК	Requires Attention	N/A
Body Style:	Wagon	Year:	2001	Engine		Attention	IN/A	
Rego No.:	BHN127	Rego Expiry:	04 Mar 2026	Oil level				1
WoF Expiry:	25 Jul 2026	Odometer:	154,384 Kms	Smoke & fu	mes		_ •	
Good No.:	27855696	VIN:	7A8H6390702001927	Engine performance				
Next Service:	159,000	Service History:	No	Noise				
Note: This report is n	•	,		Coolant cor	ndition			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a				Cooling per				
<u> </u>	ction prior to purchase and	d this can be arranged f	or an additional charge.		oses (visual)	· /		
(ey	Dust C C	reads * Dogo	ls W Significant souffs	Transmission				
S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips S R SC S S S			=	Operation		/		
				Noise				
			S	Clutch				1
			CV joints		/			
			S	Wheel bear	ings	/		
s sc				Brakes				
MACHINE		Performano	e	/				
S R SC S R SC S R SC S R SC S R S S Note: some defects and blemishes may not be displayed in the diagram			Hand brake		/			
			Tyres (lowest observed tread depth of tyres)					
				Left front			•	4.5 mm
			SR	Right front				4.5 mm
				Left rear			:	2.5 mm
				Right rear				5.0 mm
			Spare		Yes			
Body Inspection Comments				Suspension				
Side Skirts III-Fit	Side Skirts III-Fitting, Damaged			Suspension	performance	/		
				Steering pe	rformance	✓		
				Shock abso	rbers		~	
Conditions Duri	onditions During Body Inspection Dry			Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments			Operation		✓			

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Water Only, No Coolant Oil Seepage from Valve Cover, Oil Low & Leaks Left Front Shock Absorber Leaking

Interior Comments		
Seats:	Average	
Carpets:	Drivers carpet worn	
Panels:	Average	
Dashboard:	Average	
- 1-	_	

General Comments

Left Mirror Vertical Adjustment Not Working Left Door Central Locking Not Working Engine Whine

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	90,528 Kms
Inspected by: Samuel Weir				
Published by: James Scott				
Inspection Date:	15 Dec 2025			

NAME

SIGNATURE		

Sat. nav. (basic test only) Reversing camera

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Radio (basic test only)

CD (basic test only)

Number of keys Central locking Remote locking

Rear view mirrors

1

1

1 1

Ī

1

1

1

1

Head lights

Tail lights

Indicators

I have read and understood
this condition guide: