

•	Report ID:	27,861,226	Version:	1	
	Created:	23 Dec 2025			

	Basic Condition Guide		ic Condition Guide	Created: 23 Dec 2025					
	offici	<u> </u>		Created:	23 Dec 2025				
Make:	Toyota	Model:	Soarer			01/	Requires		
Body Style:	Sports Car	Year:	1993	Engine		OK	Attention	N/A	
Rego No.:	RBS151	Rego Expiry:	04 Mar 2026	Oil level			·	1	
WoF Expiry:	08 Jul 2025	Odometer:	94,500 Kms	Smoke & fu	ımes	<b>/</b>	•	1	
Good No.:	27861226	VIN:	7AT0H60XX22029701	Engine per		<b>'</b>		1	
Next Service:	0	Service History:	No	Noise	Torritance	<b>'</b>			
ote: This report is	•			Coolant co	ndition	1		<del>                                     </del>	
iagnostic testing u	ndertaken. The vehicle has h	been driven up to 50km,	Parts have not been dismantled or h from cold. The Vendor recommends a	Cooling pe		1		1	
·	pection prior to purchase ar	nd this can be arranged 	for an additional charge.		Hoses (visual)	1			
ey	Durt C	Consider the Daniel	-l-	Transmiss		-			
	C = Rust $C = CC = Rust$ $C = Rust$	Crack * = Deca Pin dent SC = Sto	als W = Significant scuffs one Chips	Operation		V	<u> </u>		
				Noise		1		1	
				Clutch				V	
	6			CV joints				V	
				Wheel bea	rings	1			
PT 6				Brakes					
	19/ 11			Performan	ce	<b>/</b>			
			PT	Hand brake	 e	1			
				Tyres (lowest observed tread depth of tyres)					
				Left front 4 m					
				Right front		4		4 m	
			Left rear		4				
			Right rear		4				
Note: some defects and blemishes may not be displayed in the diagram				Spare	Yes				
Body Inspect	ion Comments			Suspensio	n	,			
		-	el, handbrake boot, centre	Suspension	n performance	<b>'</b>			
-	e lid, and gear knob w d tool missing. Front b		as different shades panel to	Steering pe	erformance		~		
parior daok arr	a tool illiooning. I folice	oumper grille loose	•	Shock abso	orbers	<b>'</b>			
Conditions During Body Inspection Wet				Air Condit	ioning / Heater				
Under Carria	ge and Under Bonne	t Inspection Comr	nents	Operation			V		
Engine oil level over MAX. Engine oil leaks.					Electrical / Accessories				
				Head light:	5		V		
				Tail lights		<b>'</b>			
Interior Com	nents			Indicators		<b>'</b>			
Seats:	Average			Dashboard	l warning lights	<b>'</b>			
Carpets:	Average			Wipers (fro	nt & rear)	<b>'</b>			
Panels:	Average			Window w	inder FL	/			
Dashboard:	Poor			Window w	inder FR	<b>'</b>			
General Comments				Window w	inder RL			1	
ODO: 94023 kms. Left side mirror adjustment not working. A/C screen not working.					inder RR			1	
Radio not working. No high stop light. Steering wheel shakes above 40km/h. Suspension clunks. Right high beam not working.			Rear view r	mirrors		~			
2.3001.01011.010		st working.		Radio (basi	c test only)		1		

Road Conditions During Test Drive Wet Cambelt Engine Timing Mechanism **✓** Yes Evidence of Cam Belt Replacement No 80,034 Kms Eleoit Kumar Inspected by: Published by: Eleoit Kumar Inspection Date: 23 Dec 2025

I have read and understood this condition guide:

NAME			

SIGNATURE			

1

1

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)