

•	Report ID: 27,872,627		Version:	2
	Created:	30 Dec 2025		

UT	nue	S Basi	c Condition Guide	Created:	30 Dec 2025	Ve	rsion: 2	
Make:	Subaru	Model:	Legacy				Requires	
Body Style:	Sedan	Year:	2009	Funda		OK	Attention	N/A
Rego No.:	NGL688	Rego Expiry:	26 Jul 2026	Engine				
WoF Expiry:	25 Mar 2026	Odometer:	149,501 Kms	Oil level		<b>/</b>		
Good No.:	27872627	VIN:	7AT0GF0BX21003854	Smoke & fu		V		
Next Service:	102200 kms	Service History:	No	Engine performance		V		
Note: This report is	not a warranty			Noise Coolant co	ndition	V		
This report is a guide	only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or h from cold. The Vendor recommends a			V		
	ection prior to purchase an			Cooling pe		V		
Key					Hoses (visual)			
	= Rust C = C		3	Transmissi	on		<u> </u>	
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		<i>'</i>		
	W	D P		Noise		-		
				Clutch		-		
	$\sim$		(O) s	CV joints	·! n ere	-	<i>'</i>	
SPT		<u> </u>		Wheel bearings   Brakes				
Albania						<b>V</b>	l	
1			PT	Performan		V		
<u> </u>	loc II			Hand brake			t: was)	
sc				Tyres (lowest observed tread depth of tyres)  Left front 5.0 mm				
			DP	Right front				5.0 mm
				Left rear		-		5.0 mm
D P W						5.0 mn		
				Right rear Spare		Yes		
	and blemishes may not be on Comments	displayed in the diagra	am	Suspension				
body inspecti	on comments			•	n performance	<b>V</b>		
				Steering pe		· /		
				Shock abso		4		
Conditions During Body Inspection Dry					Air Conditioning / Heater			
Under Carriage and Under Bonnet Inspection Comments					ioning / ricater	V		
LF shock top mount cracking.				Operation   Electrical / Accessories				
	g-			Head lights		·		
				Tail lights		1		
Interior Comn	nents			Indicators		· /		
Seats: Average				warning lights	1			
Carpets:	Good			Wipers (fro		·		
Carpets. Good			wipers (ito	in a rear	_			

Interior Comments				
Seats:	Average			
Carpets:	Good			
Panels:	Average			
Dashboard: Good				
General Comments				

LF wheel bearing noise.

Steering knocks.

Rear CV axle inner boots split.

		T_		
Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		<b>✓</b> Yes	No	92,324 Kms
Inspected by:	Eleoit Kumar			
Published by:	Sam Huang			
Inspection Date:	18 Dec 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE		

1

1

1

1

1

1

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera