


•	Report ID: 27,877,522		Version:	1
	Created:	23 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	V		
Noise	✓		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	/	İ	
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		(3.5 mm
Right front		(6.0 mm
Left rear			1.5 mm
Right rear			1.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	/		
Window winder RL	•		
Window winder RR	/		
Rear view mirrors	/		
Tical view militors			
Radio (basic test only)	/		
Radio (basic test only)	/		
Radio (basic test only) CD (basic test only)	✓ ✓		
Radio (basic test only) CD (basic test only) Number of keys	✓ ✓ 1		
Radio (basic test only) CD (basic test only) Number of keys Central locking	✓ ✓ 1		

Make:	Holden	Model:	Captiva 5
Body Style:	suv	Year:	2015
Rego No.:	JBK115	Rego Expiry:	16 Oct 2026
WoF Expiry:	15 Dec 2026	Odometer:	201,809 Kms
Good No.:	27877522	VIN:	KL3DD2669EB063121
Next Service:	206185	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Boot struts need replacing

Tools are missing

Minor stone chips on windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

All wheel drive

Transmission leak

Interior Comments				
Seats: Drivers seat torn, Good				
Carpets: Good				
Panels:	Good			
Dashboard: Good				
General Comments				

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jaykib Collins	
Published by:	Janine Bell	
Inspection Date:	22 Dec 2025	

I have read and understood	k
this condition quide	

NAME			

SI	GN	IA.	TU	RF