

-	Report ID:	27,877,630	Version:	4
	Created:	23 Dec 2025		

Basic Condition Guide			Report ID:	27,877,630	Ve	rsion: 4		
	ome			Created:	23 Dec 2025			
Make:	Mercedes-Benz	Model:	B200				Requires	
Body Style:	Hatchback	Year:	2006			OK	Attention	N/A
Rego No.:	QYT781	Rego Expiry:	01 Apr 2026	Engine				
	18 Dec 2026	Odometer:	145,199 Kms	Oil level		/		
WoF Expiry:	27877630		WDD2452342J144927	Smoke & fu	imes	<b>/</b>		<u> </u>
Good No.:		VIN:	No	Engine per	formance	<b>V</b>		
Next Service:	155, 206 Kms	Service History:	INO	Noise		<b>/</b>		
Note: This report is This report is a quide	•	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	ndition	<b>/</b>		
diagnostic testing un	dertaken. The vehicle has bection prior to purchase an	een driven up to 50km/l	h from cold. The Vendor recommends a	Cooling pe	rformance	<b>V</b>		
Key				Radiator / I	Hoses (visual)	V		
•	= Rust C = C	Crack *= Deca	lls W = Significant scuffs	Transmiss	ion			
D = Dent P1	$\Gamma = Paint defect  P = P$	in dent SC = Sto	ne Chips	Operation		V		
	10/	SC S P SC	WSC	Noise		V		
SC	W	36 3730	W SC	Clutch				1
			288	CV joints		1		
S SC S SC					rings	1		
					Brakes			
	M 11	Performan	ce	V				
			sc	Hand brake	2	V		
S SC S SC					Tyres (lowest observed tread depth of tyres)			
					front 2.5 mm			
						2.5 mn		
						6.0 mn		
	W	SCSCSPSC	WS	Right rear				6.5 mm
Note: some defects	and blemishes may not be	displayed in the diagra	am	Spare		Yes		
Body Inspection	•			Suspension				
RR wheel centr	e cap missing.			Suspension	n performance	V		
***************************************		OLOTEDED DUE T	-0   40DED DE00**	Steering pe	erformance	1		
""THIS VEHICL	E HAS BEEN RE-RE	GISTERED DUE T	O LASPED REGO"	Shock abso		1		
Conditions During Body Inspection Dry			Air Conditioning / Heater					
Under Carriage and Under Bonnet Inspection Comments			Operation		V		Τ	
Engine cover lo					'Accessories			
Bonnet latch release handle damaged, zip tie to use release.			Head lights		V			
Intermittent eng	ine misfire at idle whe	en engine warm.		Tail lights		1		$\vdash$
Interior Comm	nents			Indicators		1		$\vdash$
Seats:	Average, drivers	seat leather crack	king		warning lights	1		$\vdash$
Jeats.	Twerage, unvers	- Cat leather Grace	Mily.	Dasiibudiu	wairing lights			-

Interior Comments			
Seats:	Average, drivers seat leather cracking.		
Carpets:	Good		
Panels:	Average		
Dashboard:	Average, steering wheel worn.		

## **General Comments**

Rear centre seatbelt buckle not buckling properly. Small cut in FL seatbelt webbing. Front window washers need adjustment. FL door speaker poor.

Side mirrors not retracting. Instrument cluster displays poor. Knock in suspension. Steering wheel isn't straight when driving straight.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Troy Smith			
Published by:	Shanna Bullion			
Inspection Date:	21 Dec 2025			

I have read and understood
this condition quide

NAME			

SIGNATURE			

1

1

1

1

1 1

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

Rear view mirrors