Basic Vehicle Condition Guide

Report ID: 17,797,514
Version: 3
Created: 30 Apr 2019

Make:	Mitsubishi	**Model:**	Triton	**Body Style:**	Utility
Year:	2012	**Registration:**	GJM4	**Reg Expiry:**	01 Jul 2019
WoF Expiry:	06 Jul 2019	**Odometer:**	125,617 Kms	**Good No:**	17797514
VIN:	MMAJNKA40CD0063C	**Next Service:**	127,500kms	**Service History:**	Yes

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

- Small stone crack in left side of windscreen.
- Screw holes on inside lips of right & left side front guards, where aerials have been attached to vehicle.
- Badge missing off rear tailgate.
- Paintwork on most body panels is marked & faded, from where stickers have been attached to vehicle.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

Interior Comments

Seats	Average
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

- Small hole in base of drivers seat.
- Screw holes in dashboard.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 90,910

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch	✔		
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5.4 mm		
Right front	6.6 mm		
Left rear	5.2 mm		
Right rear	6.4 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Xinghui Lin Date: 30 Apr 2019

I have read and understood this condition guide. Name: ..... Signature: .....