# Turners

## Basic Vehicle Condition Guide

Report ID: 17,964,102
Version: 2
Created: 12 Feb 2019

| | | | | |
|---|---|---|---|---|
| **Make:** | Ford | **Model:** | Territory | **Body Style:** SUV |
| **Year:** | 2015 | **Registration:** | HYE528 | **Reg Expiry:** 21 Jan 2019 |
| **WoF Expiry:** | 24 Dec 2019 | **Odometer:** | 129,129 Kms | **Good No:** 17964102 |
| **VIN:** | 6FPAAAJGATDK48472 | **Next Service:** | 135,000 | **Service History:** Yes |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: S, S, P SC, S, SC, S, S, P

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments
Stone chip on front windscreen
RH tail lamp chipped

### Conditions During Body Inspection: Dry

### Under Carriage & Under Bonnet Inspection Comments

### Interior Comments

| | |
|---|---|
| Seats | Average |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

### General Comments
RL power window not working
Mirror switch insecure

### Road Conditions During Test Drive: Dry

### Engine Timing Mechanism: Cambelt

### Evidence of Cam Belt Replacement: No          Kms:

| | Pass | Fail | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 6 | | mm |
| Right front | 6 | | mm |
| Left rear | 6 | | mm |
| Right rear | 6 | | mm |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | | ✔ | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | ✔ | | |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | ✔ | | |

Inspected by: Mathew Varghese          Date: 12 Feb 2019

I have read and understood this condition guide.     Name: ………………………………………………     Signature: ………………………………………