Basic Vehicle Condition Guide

Report ID: 19,477,260
Version: 1
Created: 09 May 2019

Make:	Opel	**Model:**	Vectra GL	**Body Style:**	Sedan
Year:	1992	**Registration:**	PS2808	**Reg Expiry:**	10 Aug 2019
WoF Expiry:	21 Sep 2019	**Odometer:**	288,032 Kms	**Good No:**	19477260
VIN:		**Next Service:**	N/A	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Left wing mirror is broken. Rear bumper needs refitted. Right front cv boot torn.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks gear box and engine area. Intake pipe has been taped up. Coolant needs redone. Dent in the engine sump pan.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

No service history OR service sticker on vehicle. Interior on front left and right doors is very worn and torn in places. Hoodlining - poor repair. Radio not working. Clutch is starting to slip.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes Kms: 121,600

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition		✔	
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch		✔	
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0 mm		
Right front	5.3 mm		
Left rear	3.3 mm		
Right rear	3.5 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation		✔	
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors			✔
Radio (basic test only)		✔	
CD (basic test only)			✔
Number of keys	3		
Central locking	✔		
Remote locking			✔
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Anna-Lise Ferguson Date: 09 May 2019

I have read and understood this condition guide. Name: ..... Signature: .....