# Turners

## Basic Vehicle Condition Guide

Report ID: 19,810,030
Version: 1
Created: 08 Oct 2019

| | | | | | |
|---|---|---|---|---|---|
| **Make:** | Mazda | **Model:** | CX-5 | **Body Style:** | SUV |
| **Year:** | 2015 | **Registration:** | JHS88 | **Reg Expiry:** | 09 Aug 2020 |
| **WoF Expiry:** | 14 Sep 2019 | **Odometer:** | 140,267 Kms | **Good No:** | 19810030 |
| **VIN:** | JM0KE102200333369 | **Next Service:** | 144,000 | **Service History:** | Yes |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: SC, SC, S, S, S, SC, SC, SC, P SC

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments
FL park light/DRL not working, flickers

| Conditions During Body Inspection: | Dry |
|---|---|

### Under Carriage & Under Bonnet Inspection Comments
Coolant diluted
AWD

### Interior Comments

| | |
|---|---|
| Seats | Good |
| Carpets | Average |
| Panels | Good |
| Dashboard | Good |

### General Comments

| Road Conditions During Test Drive: | Dry |
|---|---|

| Engine Timing Mechanism: | Timing Chain | |
|---|---|---|
| Evidence of Cam Belt Replacement: | Not Applicable | Kms: |

| | Pass | Fail | N/A |
|---|:---:|:---:|:---:|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | | ✔ | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | | 1.6 | mm |
| Right front | | 2 | mm |
| Left rear | | 2 | mm |
| Right rear | | 1 | mm |
| Spare | | Yes | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | ✔ | | |
| Number of keys | 1 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | ✔ | | |
| Reversing camera | ✔ | | |

| Inspected by: | Mathew Varghese | Date: | 08 Oct 2019 |
|---|---|---|---|

I have read and understood this condition guide.     Name: ………………………………………     Signature: …………………………………