Turners

Basic Condition Guide

Report ID:	24,880,015	Version:	2
Created:	08 Oct 2026		


Make:	Hyundai	Model:	Iload
Body Style:	Van	Year:	2015
Rego No.:	HYB979	Rego Expiry:	13 Oct 2027
WoF Expiry:	21 May 2027	Odometer:	319,863 Kms
Good No.:	24880015	VIN:	KMFWBX7KLEU653429
Next Service:	323,000,km's	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left & right side windscreen mouldings are missing. Roof rack need refitted down, roof rails has pull out of roof panel. Water inside indicator repeater lens on left front guard.

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Oil leak from engine.

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Small hole in fabric in base pad of drivers seat. Left front door is not locking or unlocking with central locking. Tailgate & left rear door frame seals are torn & damaged. Interior door handles missing off tailgate. Tools are missing.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Jason Young		
Published by:	Glen Charlton		
Inspection Date:	30 Sep 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Engine performance	✔		
Noise	✔		
Coolant condition	✔		
Cooling performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch	✔		
CV joints			✔
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0 mm		
Right front	6.0 mm		
Left rear	4.0 mm		
Right rear	4.5 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL			✔
Window winder RR			✔
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking		✔	
Remote locking	✔		
Sat. nav. (basic test only)			✔
Reversing camera	✔		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____