Turners

Basic Condition Guide

Report ID:	27,987,605	Version:	2
Created:	20 Feb 2026		

Make:	Honda	Model:	CRV
Body Style:	Hatchback	Year:	2007
Rego No.:	LAS233	Rego Expiry:	06 Jul 2026
WoF Expiry:	27 Jan 2027	Odometer:	172,157 Kms
Good No.:	27987605	VIN:	7AT08G7HX17005568
Next Service:	171,500 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

LF guard trim loose.
LH mirror surround cracked.
Aerial missing.
Crack in windscreen.
Water in spare wheel well.

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Surface rust on lower radiator support.

Interior Comments

Seats:	Poor
Carpets:	Good
Panels:	Poor, Both B pillar panels missing
Dashboard:	Average, Steering wheel worn

General Comments

Windscreen washer reservoir leaking.
Doesn't stay unlocked.
Spare tyre missing.
Key recognition warning.
Rear window washer needs adjusted.
Pulls to the left.
Steering knock.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Caleb Spicer Lee
Published by:	Shanna Bullion
Inspection Date:	18 Feb 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Engine performance	✔		
Noise	✔		
Coolant condition	✔		
Cooling performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	5.5 mm		
Right front	7.0 mm		
Left rear	3.0 mm		
Right rear	3.5 mm		
Spare	No		
Suspension			
Suspension performance	✔		
Steering performance		✔	
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. nav. (basic test only)			✔
Reversing camera			✔

I have read and understood this condition guide:

NAME _____

SIGNATURE _____