Turners

Basic Condition Guide

Report ID:	28,011,636	Version:	2
Created:	27 Feb 2026		

Make:	Suzuki	Model:	Swift
Body Style:	Hatchback	Year:	2017
Rego No.:	NCQ104	Rego Expiry:	02 Nov 2025
WoF Expiry:	31 Jul 2025	Odometer:	161,472 Kms
Good No.:	28011636	VIN:	7AT0GK0CX20110867
Next Service:	123859	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Coolant reservoir needs topping up.
Left hand side mirror is missing the bottom cover.
No leaks seen.
Number plate light is not working.

Interior Comments

Seats:	driver seat backrest has a tear on the outer edge.
Carpets:	Average
Panels:	radio surround panel is cracked.
Dashboard:	left hand centre vent broken.

General Comments

Front left window does not go down with the window switch.
The temperature control knob for the air conditioning has come out of place.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Bryce Steele
Published by:	Bryce Steele
Inspection Date:	27 Feb 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Engine performance	✔		
Noise	✔		
Coolant condition		✔	
Cooling performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front		2 mm	
Right front		mm	
Left rear		3 mm	
Right rear		5 mm	
Spare	N/A		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL		✔	
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)			✔
Number of keys	1		
Central locking	✔		
Remote locking	✔		
Sat. nav. (basic test only)			✔
Reversing camera	✔		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____