Turners

Basic Condition Guide

Report ID:	28,022,399	Version:	2
Created:	05 Mar 2026		

Make:	Nissan	Model:	Terrano
Body Style:	Wagon	Year:	1997
Rego No.:	HMC921	Rego Expiry:	01 May 2026
WoF Expiry:	11 Aug 2026	Odometer:	229,280 Kms
Good No.:	28022399	VIN:	7A8DH2B0706008367
Next Service:	233,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both taillights fit poorly.
LF door window monsoon damaged.
LF guard mirror cover missing.
Drivers door seal torn.
RH side mirror loose.
Rust on sunroof frame.

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Coolant is cloudy/milky.
Engine oil leaks.
Power steering oil leak.
Rear differential oil leak.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Average. Sunroof cover gets stuck.
Dashboard:	Average, steering wheel worn.

General Comments

Rear wiper blade needs replaced.
No adjustment or retraction in both side mirrors.
Drivers seatbelt doesn't retract.
Brakes are noisy when cold.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Troy Smith
Published by:	Troy Smith
Inspection Date:	05 Mar 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Engine performance	✔		
Noise	✔		
Coolant condition		✔	
Cooling performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	8 mm		
Right front	8 mm		
Left rear	5.5 mm		
Right rear	6.5 mm		
Spare			
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors		✔	
Radio (basic test only)	✔		
CD (basic test only)			✔
Number of keys	2		
Central locking	✔		
Remote locking			✔
Sat. nav. (basic test only)			✔
Reversing camera			✔

I have read and understood this condition guide:

NAME _____ **SIGNATURE** _____