Turners

Basic Condition Guide

Report ID:	28,180,825	Version:	1
Created:	19 Jun 2026		

Make:	Mitsubishi	Model:	Outlander
Body Style:	Wagon	Year:	2008
Rego No.:	MTH676	Rego Expiry:	11 May 2026
WoF Expiry:	17 Mar 2027	Odometer:	195,265 Kms
Good No.:	28180825	VIN:	7AT0CJ3MX20205053
Next Service:	202,000km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Right side of front bumper & right bottom moulding are not fitting properly. Right front spot light surround is missing. Right front inner guard panel is cracked & broken, has bottom part missing. Plastic cover missing off left rear roof rack bracket.

Conditions During Body Inspection	Dry

Under Carriage and Under Bonnet Inspection Comments

Minor oil leak from engine.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Average
Dashboard:	Good

General Comments

Minor damage to speedo display screen on dashboard. Plastic covers missing from around rear seat mounting brackets.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Jason Young		
Published by:	Sara Haggerty		
Inspection Date:	11 Jun 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Engine performance	✔		
Noise	✔		
Coolant condition	✔		
Cooling performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	3.5 mm		
Right front	4.0 mm		
Left rear	7.0 mm		
Right rear	7.0 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	1		
Central locking	✔		
Remote locking	✔		
Sat. nav. (basic test only)			✔
Reversing camera	✔		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____