# Turners — Basic Condition Guide

| | | | |
|---|---|---|---|
| Report ID: | 28,531,302 | Version: | 1 |
| Created: | 15 Oct 2026 | | |


| | | | |
|---|---|---|---|
| Make: | Toyota | Model: | Hiace |
| Body Style: | Van | Year: | 2018 |
| Rego No.: | LMK726 | Rego Expiry: | 05 Jul 2027 |
| WoF Expiry: | 09 Jul 2027 | Odometer: | 76,456 Kms |
| Good No.: | 28531302 | VIN: | JTFPT22P200021354 |
| Next Service: | 91000 | Service History: | No |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips




Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

| | |
|---|---|
| Conditions During Body Inspection | Wet |

## Under Carriage and Under Bonnet Inspection Comments

Rear wheel drive
Right rear sill bent

## Interior Comments

| | |
|---|---|
| Seats: | Good |
| Carpets: | Good |
| Panels: | holes drilled/cut- good |
| Dashboard: | holes drilled/cut- good |

## General Comments

A/C not cold

| | | | |
|---|---|---|---|
| Road Conditions During Test Drive | Wet | | |
| Engine Timing Mechanism | Cambelt | | |
| Evidence of Cam Belt Replacement | ☐ Yes | ☑ No | Kms |
| Inspected by: | Jesse Amey | | |
| Published by: | Jesse Amey | | |
| Inspection Date: | 15 Oct 2026 | | |

| | OK | Requires Attention | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Engine performance | ✔ | | |
| Noise | ✔ | | |
| Coolant condition | ✔ | | |
| Cooling performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 6.4 mm | | |
| Right front | 6.9 mm | | |
| Left rear | 8.3 mm | | |
| Right rear | 8.3 mm | | |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | | ✔ | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | | | ✔ |
| Window winder RR | | | ✔ |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | | | ✔ |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. nav. (basic test only) | | | ✔ |
| Reversing camera | ✔ | | |

I have read and understood this condition guide:

**NAME** _____ **SIGNATURE** _____