

Report ID: 21,209,229 Version: 1 29 Feb 2024 Created:

| Make: | Nissan | Model: | Navara | Body Style: | Utility | | Pass | Fail | N/A | |
|---|---|----------------------|------------------------|--------------------|----------------------|--|--------|--------|----------|--|
| Year: | 2018 | Registration: | LMY209 | Reg Expiry: | 26 Jul 2024 | Engine | | | | |
| WoF Expiry: | 07 Oct 2024 | Odometer: | 167,205 Kms | Good No: | 21209229 | Oil level | ~ | | | |
| VIN: | MNTEB4D23A000057(| Next Service: | 180900 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty a guide only. Conside | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | | |
| diagnostic tes | sting undertaken. The v | vehicle has beer | n driven up to 50km/h | from cold. The | Vendor recommends | Cooling System | | | <u>.</u> | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | 1 | |
| | | | | | | Performance | ~ | | | |
| Key: | sc | -0 | | -161- | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | RE | A U | | | The second | Transmission | - | | <u> </u> | |
| D = dent | S PT SC | | | | | Operation | ~ | | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | | |
| C = crack | | | | + | | Clutch | ~ | | | |
| P = pin dent | | | | | 세비 | CV joints | ~ | | - | |
| * = decals | - 1916 | | | The | ETTPS- | Wheel bearings | ~ | | | |
| SC = stone chi | | 26 | | 10L | | Brakes | • | | L | |
| W = significant | t scuffs W | $- \emptyset$ | | | | Performance | ~ | | | |
| | | Note: som | ne defects & blemishes | may not be disc | laved in the diagram | Hand Brake | ~ | | | |
| Body Insp | ection Comments | | | , | | Tyres (lowest observed tread | - | oftyre | <u> </u> | |
| | | | | | | Left front 5.0 mm | | | | |
| | | | | | | Right front | _ | | mm | |
| | | | | | | Left rear | | .0 | mm | |
| | | | _ | | | Right rear | | .0 | | |
| Conditions During Body Inspection: Dry | | | | | | Spare | 3.0 mm | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | | Yes | | | |
| | inage a onder bor | iner inspectie | <u>eonnents</u> | | | Suspension | | | 1 | |
| | | | | | | Suspension performance Steering performance | ~ | | | |
| | | | | | | | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | 1 | |
| Interior Comments | | | | | | Operation | | | | |
| | Average | | | | | Electrical / Accessories | | | 1 | |
| Seats | | | | | | Head lights | ~ | | | |
| Carpets | Average | | | | | Tail lights | ~ | | | |
| | Average | | | | | Indicators | ~ | | | |
| Panels | Avelage | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | | |
| | - | | | | | Window winder FL | ~ | | | |
| Gonoral | Comments | | | | | Window winder FR | ~ | | | |
| | | | | | | Window winder RL | | | ~ | |
| | | | | | | Window winder RR | | | ~ | |
| | | | | | | Rear view mirrors | ~ | | <u> </u> | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | | | ~ | |
| | | | | | | Number of keys | 2 | | | |
| Road Con | ditions During Test | Drive: | Dry | | | Central locking | ~ | | | |
| Engine Tim | ning Machanism | T: | Chain | | | Remote locking | ~ | | | |
| - | ning Mechanism: | Timing (| | V acation | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ | |
| Inspected | d by: Greg Morgan | | | | | Date: 29 Feb 20 | 24 | | | |

I have read and understood this condition guide.

Name:

Signature: