

I have read and understood this condition guide.

Report ID: 22,811,522 Version: 3 11 Mar 2024 Created:

Signature: .....

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2020	Registration:	NDZ920	Reg Expiry:	26 May 2024	Engine			
WoF Expiry:	26 Nov 2024	Odometer:	67,469 Kms	Good No:	22811522	Oil level	~		
VIN:	MPBUMFF50LX30805	Next Service:	77000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta harra nat	la a constanti a di c	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	v		
Key:		-0	S L	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation 🖌			
R = rust PT = paint defe				r i M	JHIH	Noise	~		
C = crack				+	D	Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	sc 916			-NL	ELIPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S D						Performance	~		
		Note: son	he defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftvre	() ()
LH door mirror indicator repeater cracked.						Left front 5.0 mm			
						Right front	5		 mm
						Left rear	5		mm
			2			Right rear			
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
4Wheel driv	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation 🖌			
Good									
Seats							~		
Carpets	Good					Tail lights Indicators	~		
	Good						~		
Panels						Dashboard warning lights Wipers (front & rear)	V 		
Dashboa	rd Good					• · · ·	~		
						Window winder FL	<b>v</b>		
General Comments						Window winder FR Window winder RL	<b>v</b>		
							V 		
						Window winder RR Rear view mirrors	<b>v</b>		
							<b>v</b>		
						Radio (basic test only)	~		
						CD (basic test only)			
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
						Reversing camera	~		
Inspected by: Rajesh Mayan Date: 07 Mar 2024									

Name: .....