

... C

Engine

Oil level

Noise

Smoke & fumes

Coolant condition

Performance

Service	History:	No

Note: This report is not a warranty

TMAH351CMMJ14636 Next Service:

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

46000

Performance SC W P SC W S Key: Radiator / Hoses (visual) S = scratch Fransmission D = dent S W SC W Operation R = rustNoise PT = paint defect C = crackClutch P = pin dent CV joints S * = decals Wheel bearings SC = stone chips Brakes W = significant scuffs P SC W Performance Note: some defects & blemishes may not be displayed in the diagram Hand Brake **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front **Right front** Left rear **Right rear** Conditions During Body Inspection: Dry Spare Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Interior Comments

Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) ~ Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) ~ Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 1

Inspected by: Donovan Matara

27 Feb 2024 Date:

Report ID:	23,011,192
Version:	2
Created:	14 Mar 2024

Pass

~

V

V

~

V

V

V

V

~

V

~

V

3.0

3.5

5.0

6.0

V

V

~

V

Yes

Fail

N/A

V

mm

mm

mm

mm

I have read and understood this condition guide.

Name:

Signature: