

Report ID: 23,075,063 Version: 1 10 Apr 2024 Created:

Make:	Ford	Model:	Transit	Body Style:	Van		Pass	Fail	N/A
Year:	2011	Registration:	FYZ36	Reg Expiry:	25 Sep 2024	Engine	1	1	
WoF Expiry:		Odometer:	232,226 Kms	Good No:	23075063	Oil level	~		┌──┤
VIN:	WF0XXXTTFXBE15677	Next Service:	240,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S D SC SC		S P SC		S D SC	Performance	~		
Key:	13030 [[3	-0		500-	3030	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s AR			20	HILLS	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TTM.	S D SC	Clutch	~		
P = pin dent	S P SC				74IIL	CV joints			~
* = decals		10		10	SC SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = Significan	SD S	C	S D S P		S P SC	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
R/H tail light chipped on edge.						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres)		
Rusty scratches & chips around vehicle.						Left front	Left front 5 n		
Chipped windscreen. Rear step bent.						Right front	4	1	mm
neur step s						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare Yes			
<u>Under Ca</u>	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Engine oil l	eaks.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	V		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Left seat ri	ipped.				Head lights	~		
	Hole on dr	rivers side.				Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Steering w	vheel worn, screv	v holes.			Wipers (front & rear)	~		
Dashboa	ra	,				Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
6 speed manual diesel, high roof, long wheelbase van.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Daryll Timms					Date: 10 Apr 202	24		

I have read and understood this condition guide.

Name:

Signature: