

Report ID: 23,076,138 Version: 1 02 Apr 2024 Created:

Make:	Volkswagen	Model:	T6	Body Style:	People Mover		Pass	Fail	N/A
Year:	2019	<b>Registration:</b>	MNP388	<b>Reg Expiry:</b>	21 Aug 2024	Engine			
WoF Expiry:	07 Sep 2024	Odometer:	134,985 Kms	Good No:	23076138	Oil level	~		
VIN:	WV2ZZZ7HZKH16473	Next Service:	unknown	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		P SC P SC		SC	Performance	V		
Key:	ISC (C	-0	P SC P SC	-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HILS	Operation	V		
PT = paint defe				$\left( \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	110				세비	CV joints	~		
* = decals	PSC 916			-Jul	ELD'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC P SC P SC W S SC W						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Jack & tools missing. Drivers door seal damaged.						Left front 7 mm			
						Right front		, 7	mm
						Left rear		, 7	mm
						Right rear			mm
Conditions During Body Inspection: Dry						Right rear 7 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		<b>-</b>				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation 🖌			
Seats Average						Head lights			
Sears							~		
Carpets	Average					Tail lights Indicators	<b>v</b>		
	Cargo area	a trim holes, arab	handles need refitting	q			~		
Panels		-		-		Dashboard warning lights	<b>v</b>		
Dashboa	rd Ashtray / t	rinket tray lid no	t closing.			Wipers (front & rear) Window winder FL	~		
							~		
General (	omments					Window winder FR	~		
General Comments AWD 7 seater diesel auto van.						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Cambel				Remote locking	~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
		ement. N	10	1/1115.		Reversing camera	~		
Inspected by: Daryll Timms Date: 02 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....