

Basic Vehicle Condition Guide

Report ID: 23,077,697

Pass

~

~

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

26 Apr 2024 Created:


Fail

N/A

Make: Model: Toyota Hiace **Body Style:** Van Year: 2018 Registration: LGW788 Reg Expiry: 26 Sep 2024 **Odometer:** WoF Expiry: 08 Apr 2024 156,410 Kms **Good No:** 23077697 VIN: JTFHT02P105030963 **Next Service:** 158000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Hardwood panels cargo area left and right minor damage Scrape on van nose

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Clean

Interior Comments			
Seats	Rip in centre seat and small hole in rear		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Manual pull out step on left rear door 10 Seater Minibus

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Allan McLay

Evidence of Cam Belt Replacement: Kms: 150,303 Yes

ormance ator / Hoses (visual mission ation e th inits el bearings formance I Brake (lowest observed to front	V		V
nission ation e th ints el bearings s ormance I Brake (lowest observed t	V		V
ation ch	~		V
e ch	~		V
ch ints el bearings s ormance I Brake (lowest observed t	~		V
ints el bearings s ormance d Brake (lowest observed t	~		V
el bearings s rmance I Brake (lowest observed tront t front	~		
ormance I Brake (lowest observed to	~		
ormance I Brake (lowest observed t front t front	~		
I Brake (lowest observed t front t front	~		
(lowest observed t Front t front	ead depth		1
ront t front	ead depth		
front		of tyre	<u>'</u> s)
	4	.0	mm
	3	.5	mm
ear	6	.5	mm
rear	3	.5	mm
9		Yes	
nsion			
ension performan	e 🗸		
ring performance	<i>V</i>		
k absorbers	~		
nditioning / Heat	er	!	,
ation	~		
cal / Accessories	•		
llights	~		
ghts	v v		
Indicators			
Dashboard warning lights			
ers (front & rear)	~		
low winder FL	~		
low winder FR	~		
low winder RL			~
Window winder RR			~
Rear view mirrors			
Radio (basic test only)			
CD (basic test only)			
ber of keys	2	•	
Central locking			
ote locking	~		
lav. (basic test onl	_		~
low winder FL low winder FR low winder RL low winder RR view mirrors o (basic test only) basic test only) ber of keys ral locking ote locking	\(\times \) \(\t		

I have read and understood this condition guide.

Name:

Signature:

05 Mar 2024

Reversing camera