

Report ID: 24,391,103 Version: 4 02 Nov 2023 Created:

Make:	Suzuki	Model:	Swift	Body Style: Hatchback		Pass	Fail	N/A
Year:	2017	Registration:		Reg Expiry:	Engine			
		Odometer:	33,879 Kms	Good No: 24391103	Oil level	~		
VIN:	7AT0GK0CX23100615			Service History: No	Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				Performance	~		
	port is not a warranty				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.								
		_			Performance	v		
Key:		-0			Radiator / Hoses (visual)	~ ~		
S = scratch					Transmission			
D = dent								<u> </u>
R = rust					Operation Noise	~ ~		
PT = paint defe C = crack	ect M				Clutch	~		
P = pin dent	Ho							~
* = decals	- MIR				CV joints Wheel bearings	~		
SC = stone chips					Wheel bearings			L
W = significant scuffs								<u> </u>
		Nata		may not be disclosed in the discus	Performance	~		
Body Insp	pection Comments	Note: som	he defects & biemisnes	may not be displayed in the diagram	Hand Brake		<u> </u>	Ļ
					Tyres (lowest observed tread depth of tyres)			
					Left front	7.0		mm
					Right front	7.0)	mm
					Left rear	7.0)	mm
Conditions During Body Inspection: Dry					Right rear	7.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare	N/A		
					Suspension			
FWD					Suspension performance	~		
					Steering performance	~		
					Shock absorbers	~		
					Air Conditioning / Heater			
Interior Comments					Operation 🖌			
Good					Electrical / Accessories			
Seats	Good				Head lights	~		
Carpets	Good				Tail lights	~		
	Card				Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dashboa	rd Good				Wipers (front & rear)	~		
					Window winder FL	~		
					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	2		
Road Conditions During Test Drive: Dry Central locking						~		
Remote locking						~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera	~		
Inspected by: Todd Cullum Date: 31 Oct 2023								

I have read and understood this condition guide.

Name:

Signature: