

Report ID: 24,413,276 Version: 1 01 Oct 2023 Created:

Make:	Volkswagen	Model:	Crafter	Body Style:	Van		Pass	Fail	N/A
Year:	2018	Registration:	LTM701	Reg Expiry:	06 Nov 2023	Engine			
WoF Expiry:	28 Nov 2023	Odometer:	227,971 Kms	Good No:	24413276	Oil level	~		
VIN:	WV1ZZZSYZK9004662	Next Service:	212000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	sc	-0	S SC S SC	-161-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~		
						Clutch	•		~
P = pin dent						CV joints			~
*=decals SC 919 SC						Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs SC S P SC S SC P SC						Performance			
		Noto: con				Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram									
Lf hub cap damaged/both sill dented/						Tyres (lowest observed tread depth of tyres)			
						Left front		.5	mm
						Right front		.5	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear 6.5		mm	
Under Corriges & Under Depart Increation Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments 2wd/engine oil leak further investigation needed/						Suspension			
2wa/engine	e oli leak further investig	gation needed/				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments driver bottom pad damaged						Electrical / Accessories			
Seats	driver both	om pad damage	d			Head lights	~		
Carpets	hole in dri	ver side				Tail lights	~		
						Indicators	~		
Panels	scratch an	a worn				Dashboard warning lights		~	
Dashboa	rd worn butte	ons on dash				Wipers (front & rear)	~		
	iu					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			<
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Centra							~		
			-			Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
								•	
Inspected by: Uriah Pepene Date: 01 Oct 2023									

I have read and understood this condition guide.

Name:

Signature: