

Basic Vehicle Condition Guide

Report ID: 24,444,646

Version: 2

Created: 01 Dec 2023

Make: Mazda Model: Demio **Body Style:** Hatchback

Year: 2014 WoF Expiry: 29 Nov 2024

VIN:

Registration: **Odometer:**

Reg Expiry:


Good No: 24444646

Next Service: 110,000 km **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

100,691 Kms



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Pnp

Conditions During Body Inspection:

Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Allan Young

Name:

Pass Fail N/A Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 6 mm Left rear mm Right rear 6 mm Spare N/A Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

~

01 Dec 2023

Signature:

Date: