



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,499,823
Version:	1
Created:	12 Dec 2023

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X23015141
Year:	2016	Odometer:	77,240 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior	
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	78	Under Carriage	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	79	Sun Roof Operation	•
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		80	Front Windscreen (no chips)	Good	
4	High Stop Light	✓	Transmission and Drive		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good	
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		84	Rear Wiper Blade	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	7.5	85	R/H Mirror	Good
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	7	86	L/H Mirror	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	5.5	87	L/F Guard	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	5.5	88	R/F Guard	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	N/A	89	L/H Doors	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	90	R/H Doors	Good
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		91	L/H Sill	Good	
15	Number Plate Light	✓	Brakes		67	AC Operation	✓	92	R/H Sill	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	95	Rear Bumper	Good
19	Rev Counter	✓	Keys and Locking		71	Seat Heaters	•	96	Roof	Good	
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	97	Bonnet	Good
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Good	99	Mud Flaps	✓
23	Window Opener FR	✓	Engine		75	Carpets	Good	100	WOF	✓	
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Good			
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Good			
26	Rear View Mirrors	✓	52	Performance	✓						
27	Radio (Basic Test Only)	✓	53	Noise	✓						
28	CD (Basic Test Only)	✓	54	Starter Motor	✓						
29	Boot Open Switch	✓									

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

**Turners Certification Key:**  
✓ = Pass  
X = Fail  
• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	12 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	