

Report ID: 25,145,623 Version: 2 21 Feb 2024 Created:

Make:	Volkswagen	Model:	Golf	Body Style: Hatchback][Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:	Engine			1
WoF Expiry:		Odometer:	29,261 Kms	Good No: 25145623	Oil level	~		
VIN:	WVWZZZAUZEW3660	Next Service:	39,200 km	Service History: No	Smoke & fumes	~		
					Performance	~		<u> </u>
Note: This re	port is not a warranty	aration is made	for ago and milaago	Parts have not been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
					Coolant condition	ו וו		
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch D = dent					Transmission			
D = dent R = rust					Operation	~		
PT = paint defe		r I			Noise	~		
C = crack					Clutch			~
P = pin dent	HID				CV joints	~		
* = decals	- Alt				Wheel bearings	~		
SC = stone chips W = significant scuffs					Brakes			
vv – significali					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be displayed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)			25)
					Left front	7	,	mm
					Right front	6	j	mm
					Left rear	7	,	mm
Conditions During Body Inspection: Dry					Right rear	7	7 mm	
					Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
f w d					Suspension performance	~		
					Steering performance	~		
					Shock absorbers	~		
					Air Conditioning / Heater			
					Operation	~		
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
Carpote	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dashboa	rd Good				Wipers (front & rear)	~		
Dashboa	iu .				Window winder FL	~		
					Window winder FR	~		
<u>General C</u>	<u>Comments</u>				Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		
Road Conditions During Test Drive: Dry Central locking						~		
F			_		Remote locking	~		
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only)								~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:	Reversing camera	~		
Inspector	d by: Takaya Murayar	ma			Date: 21 Feb 20	24		
	a ~y unaya murayar							

I have read and understood this condition guide.

Name:

Signature: