

Report ID: 25,521,072 Version: 4 Created: 14 May 2024

| Make: | Honda | Model: | Integra | Body Style: | Sedan | | Pass | Fail | N/A |
|---|--------------------------|----------------------|------------------------|--------------------|--------------|--|------|--------|----------|
| Year: | 2004 | Registration: | JPR980 | Reg Expiry: | 01 Sep 2024 | Engine | | | |
| WoF Expiry: | 27 Jun 2024 | Odometer: | 64,763 Kms | Good No: | 25521072 | Oil level | ~ | | |
| VIN: | 7AT08G0RX15200832 | Next Service: | 74,000km | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | SPTW 66 | | | TIN | HILW | Operation | ~ | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | - |
| * = decals | sc 916 | | | - AL | EITR | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S D W S W D | | | | | | Performance | ~ | | |
| | | Note: con | | | | Hand Brake | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | - | ofture | |
| Windscreen stone chips | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | - | .0 | mm |
| | | | | | | Right front | - | .0 | mm |
| | | | | | | Left rear | | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | - | | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | - | inet inspectio | <u>on comments</u> | | | Suspension | | | 1 |
| Front whee | drive | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | 1 | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ird | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | | | ~ |
| | | | | | | Window winder RR | | | ~ |
| | | | | | | Rear view mirrors | ~ | | 1 |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | шу | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | • | | •• | | | | | | |
| Inspected by: Rowan Fey Date: 25 Jan 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: