

Report ID: 25,557,695 Version: 8 Created: 18 May 2024

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	GBY888	Reg Expiry:	01 Sep 2024	Engine	1	i	<u> </u>
WoF Expiry:	28 Feb 2025	Odometer:	135,751 Kms	Good No:	25557695	Oil level	~		1
VIN:	WVWZZZ6RZCU00182	Next Service:	142000	Service Histor	y: Yes	Smoke & fumes	~		+
						Performance	~		+
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		+
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		1
						Performance	~		
Key:		-0	ls	-161-		Radiator / Hoses (visual)	~		+
S = scratch						Transmission			L
D = dent	SD 6/6			10	EII SD	Operation	~		1
R = rust				\int		Noise	~		-
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	sc PIK				ENR	Wheel bearings	~		+
SC = stone chips						Brakes			
W = significant scuffs SD W SD S W SD						Performance 🖌			Τ
						Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread	•		
Windscreen stone chips.						Left front		,	
							5.0		mm
						Right front		.0	mm
						Left rear	-	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
-						Suspension			1
2Wheel driv	/e.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
curpets	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
	•					Window winder FR	~		
General Comments 12V port faulty in centre console						Window winder RL	~		
12V port fa	ulty in centre console					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Rajesh Mayan Date: 07 Feb 2024									
I have read and understood this condition guide. Name:									