

Report ID: 25,590,719 Version: 1 23 Feb 2024 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2019	Registration:	MFK842	Reg Expiry:	25 Mar 2024	Engine			
WoF Expiry:		Odometer:	45,273 Kms	Good No:	25590719	Oil level	~		
VIN:	JM0BN547810268893			Service Histor		Smoke & fumes	~		
			5.200			Performance	~		
	oort is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	P	-0	ls		P	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
						· ·	~		
PT = paint defect C = crack						Noise Clutch	~		
C = Crack P = pin dent	Ho								~
* = decals						CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			1
						Performance	~		
Body Insp	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		Ļ
RF door sill seal torn.						Tyres (lowest observed tread depth of tyres)			
Front tyres inner and outer edges worn. Front bumper refit right side.						Left front	3		mm
RL door window moulding damage.						Right front	-	3 mm	
Cargo area iack missing.						Left rear	5 mm		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
					Spare				
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD Rear brake pads getting low.						Suspension performance	~		
	gg					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Eleoit Kumar Date: 23 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: