

Report ID: 25,593,991 Version: 1 04 Mar 2024 Created:

Make:	BMW	Model:	Х3	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:		Reg Expiry:	05 Dec 2024	Engine			L
WoF Expiry:		Odometer:	169,237 Kms	Good No:	25593991	Oil level	~		
VIN:	WBAPC720X0WG6228	Next Service:		Service Histor		Smoke & fumes	~		
			179200			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	SC	-0	P D			Radiator / Hoses (visual)	~		
S = scratch	Se	20		10/2	\mathbf{x}	Transmission	V		
D = dent				The	EID S	Operation			<u> </u>
R = rust				10		· · · · · · · · · · · · · · · · · · ·	~		
PT = paint def	ect			+		Noise	~		
C = crack P = pin dent	Ht			-		Clutch			~
* = decals	PSC DC					CV joints	~		
SC = stone chi	ps US			10	\$P	Wheel bearings	~		
W = significant scuffs W P						Brakes			<u> </u>
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
R/R Wheel centre cap missing,						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0)	mm
						Right front	4.0)	mm
						Left rear	4.0)	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		
					Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	_		-
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L									<u> </u>
Inspected by: Chris Buckley Date: 22 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: