

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends

Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Coolant condition V Performance SC SC Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S Operation V R = rustNoise V PT = paint defect SC C = crackClutch V P = pin dent CV joints ~ SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs SC SC SC Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 6.5 **Right front** 6.5 mm Left rear 5.5 mm **Right rear** 5.5 mm Conditions During Body Inspection: Wet Spare N/A Under Carriage & Under Bonnet Inspection Comments Suspension 4wd/ Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Average Head lights Seats 1 Tail lights 1 Average Carpets Indicators ~ Average Dashboard warning lights 1 Panels Wipers (front & rear) 1 Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors 1 Radio (basic test only) V CD (basic test only) V Number of keys 1 ~ Central locking **Road Conditions During Test Drive:** Wet Remote locking V

Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable

Inspected by: **Uriah Pepene**

12 Mar 2024 Date:

Sat. Nav. (basic test only)

Reversing camera

Report ID: 25,614,634 Version: 1 12 Mar 2024 Created:

Pass

~

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail

I have read and understood this condition guide.

Name:

Kms:

Signature:

1

~