

Report ID: 25,616,552 Version: 3 07 Mar 2024 Created:

| Make: | Suzuki | Model: | Swift | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|-------------------|--|---------------------------------------|--------|------|----------------------|
| Year: | 2012 | Registration: | | Reg Expiry: | 14 Nov 2024 | Engine | | | <u> </u> |
| WoF Expiry: | | Odometer: | 127,882 Kms | Good No: | 25616552 | Oil level | ~ | | |
| VIN: | JSAFZC82S00129969 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | | | Operation V | | | |
| R = rust | | | | 10 | | · · · · · · · · · · · · · · · · · · · | | | <u> </u> |
| PT = paint def | ect | | | + | D | Noise | ~ | | |
| C = crack P = pin dent | Ht | KI | | | | Clutch | | | ~ |
| * = decals | sc dr | | | | | CV joints | ~ | | |
| SC = stone chi | ps US | | | 10 | | Wheel bearings | ~ | | |
| W = significant scuffs S D S D S D S D S D | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | <u> </u> |
| Body Ins | pection Comments | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Windscreen stone chips | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | 3. | 0 | mm |
| | | | | | | Right front | 3. | 0 | mm |
| | | | | | | Left rear | 3. | 0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 4.0 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Front whee | l drive | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | . Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ird | | | | | Window winder FL | ~ | | <u> </u> |
| | I | | | | | Window winder FR | ~ | | |
| General (| <u>Comments</u> | | | | | Window winder RL | ~ | | <u> </u> |
| | | | | | | Window winder RR | ~ | | <u> </u> |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | L |
| Pood Car | ditions During Ter | t Drivo: | | | | Central locking | 2 V | | |
| | ditions During Tes | | Dry | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | <i>v</i> <i>v</i> |
| | • | | | | | | | | |
| Inspected by: Rowan Fey Date: 05 Mar 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: