

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismant		Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomr a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	imends	Cooling System			
		Coolant condition	~		
		Performance	~		
	_	Radiator / Hoses (visual)	~		
S = scratch D = dent		Transmission	I		
R = rust SC W	SC	Operation	~		
PT = paint defect		Noise	~		
C = crack		Clutch			~
P = pin dent		CV joints	~		
*= decals SC 919		Wheel bearings	~		
SC = stone chips		Brakes			
W = significant scuffs W D W		Performance	~		
Redu Inspection Comments Note: some defects & blemishes may not be displayed in the dia	iagram	Hand Brake	~		
body inspection comments	5	Tyres (lowest observed tread	-	of tyre	es)
Minor stone chips on windscreen		Left front	3		mm
		Right front	1.9		mm
		Left rear	3.5		mm
Can ditiana Duning Dadula mantian		Right rear	2		 mm
Conditions During Body Inspection: Dry		Spare	2	Yes	
Under Carriage & Under Bonnet Inspection Comments		Suspension		163	
· · · · · · · · · · · · · · · · · · ·		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater	•		
		Operation	~		
Interior Comments		Electrical / Accessories			
Seats Good		Head lights	~		
Good		Tail lights	~		
Carpets		Indicators	~		
Panels Good		Dashboard warning lights	~		
Good		Wipers (front & rear)	~		
Dashboard		Window winder FL	~		
		Window winder FR	~		
General Comments		Window winder RL			~
Drives well		Window winder RR			~
		Rear view mirrors	~		
		Radio (basic test only)	v		
		CD (basic test only)	V		
		Number of keys	2		
Road Conditions During Test Drive: Dry		Central locking	~		
Road Conditions During Test Drive: Dry		Remote locking	~		
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)	•		~
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera	~		
···		<u> </u>	-		I
Inspected by: Jaykib Collins Date: 20 Mar 2024					

I have read and understood this condition guide.

Name:

Signature:

Report ID: 25,627,857 Version: 1 20 Mar 2024 Created:

Pass

V

V

V

Fail

N/A

Basic Vehicle Condition Guide