

Report ID: 25,637,036 Version: 1 03 Apr 2024 Created:

Make:	Hyundai	Model:	120	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GZE929	<b>Reg Expiry:</b>	30 Jul 2024	Engine			
WoF Expiry:	26 Jul 2024	Odometer:	69,851 Kms	Good No:	25637036	Oil level	~		
VIN:	MALBB51CMEM55351	Next Service:	77000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	inarge.	Coolant condition	~		
	S P SC W		P SC W P SC W		SC W	Performance	~		
Key:	L3F3CW [[	-0			30.11	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust SC W D D S						Operation	~		
PT = paint defect						Noise	~		
C = crack					W	Clutch			~
P = pin dent	LEDT HID				74116	CV joints	~		
* = decals S PT 9 9 S D R PT S						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuris S P SC S P SC W S D S SC						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
A pillars need paint , paint flaking ,mirror casings need paint ,						Tyres (lowest observed tread depth of tyres)			es)
						Left front 4 m			mm
						Right front	4	1	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4 m		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deckler	rd Average					Wipers (front & rear)	~		
Dashboa	iu ý					Window winder FL	~		
	-					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Drives okay	,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 03 Apr 2024									
Inspected by. Donovan Matara Date: 03 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....