

Report ID: 25,637,117 Version: 4 19 Apr 2024 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A	
Year:	2018	Registration:	LFG62	Reg Expiry:	14 Feb 2024	Engine		-	<u> </u>	
WoF Expiry:		Odometer:	116,042 Kms	Good No:	25637117	Oil level	~			
VIN:	MPATFS85JHT009017	Next Service:		Service Histor		Smoke & fumes	~			
			,			Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	S P SC	-0	S D R SC S P			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation	~			
R = rust				1 M	JHIH	Noise	~			
PT = paint defe C = crack				+		Clutch	~			
P = pin dent	Ho					CV joints	~			
* = decals	SRSC 91			AL.	EII PR	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S R SC S D P S R P						Performance	~			
		Note: som		may not be disn	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•			
						Tyres (lowest observed tread depth of tyres) Left front 5.0				
								.0	mm	
						Right front		.0	mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
	mage & onder bor	meenspeede	<u>in comments</u>			Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Drivers Seat Torn Bear Seats Stained					Electrical / Accessories					
Seats						Head lights	~			
Carpets	Poor					Tail lights	~			
	Average					Indicators	~			
Panels	Avelage					Dashboard warning lights		~		
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~			
Gonoral	ommonts]	Window winder FR	~		<u> </u>	
<u>General Comments</u>						Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
Enging Ti	ning Machanism	Timina	Chain			Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~	
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Samuel Weir Date: 20 Mar 2024										

I have read and understood this condition guide.

Name:

Signature: