

Report ID: 25,655,792 Version: 2 26 Mar 2024 Created:

Make:	Hyundai	Model:	Veloster	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	MEN628	Reg Expiry:	02 Dec 2024	Engine	1	I	
WoF Expiry:	14 Dec 2024	Odometer:	117,249 Kms	Good No:	25655792	Oil level	~		
VIN:	KMHTC61DVCU08282	Next Service:	115,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			I
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition		~	
						Performance	~		
Key:	SD W	-0	S W	\square	S P W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s dla			TIN	HILC	Operation	~		
R = rust PT = paint defe				$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	110				7414	CV joints	~		
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S D W						Performance	~		
Podulac		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	depth	of tyre	es)
								mm	
						Right front		5 mr	
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	-		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD						Suspension performance	~		
Oil leaking	from engine					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	-	~	
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	-		~
Battery needs to be replaced , has been tested.						Window winder RR			~
Positive battery terminal loose . ,missing jack and tools . Ac 11c and heater at 53 c					Rear view mirrors	~			
Faulty cent						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking		~	
			ЛУ			Remote locking		~	
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)		-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	-								_ -
Inspected by: Allan Young Date: 26 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: