

Basic Vehicle Condition Guide

Report ID: 25,656,596


Version: 6

Created: 07 May 2024

Make: LDV Model: T60 **Body Style:** Utility Year: 2019 Registration: LZR556 Reg Expiry: 18 Dec 2023 WoF Expiry: **Odometer:** 24 Apr 2025 100,140 Kms **Good No:** 25656596 VIN: LSFAM11A1JA100960 Next Service: 110,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Tuff Deck Modified

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Poor	
Carpets	Poor	
Panels	Good	
Dashboard	Good	

General Comments

No Spare Wheel Tools

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Samuel Weir Date: 28 Mar 2024

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
'		
~		
l depth	of tyre	es)
8	.0	mm
8.0		mm
8	.0	mm
8.0		mm
Yes		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
		_
-		
-		
1		
-		./
1		<i>V</i>
1		<i>V</i>
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

Signature: