

Report ID: 25,672,587 Version: 2 17 May 2024 Created:

Year: 20 WoF Expiry: 20 VIN: VI <u>Note: This repor</u> This report is a diagnostic testir	2eugeot 2008 26 Mar 2025 /F34CRHRJ55104782	Model: Registration: Odometer:	308 EKR196 167,725 Kms	Body Style: Reg Expiry: Good No:	Hatchback 04 May 2024 25672587	Engine Oil level	Pass	Fail	N/A
WoF Expiry: 26 VIN: VI Note: This report This report is a diagnostic testin	26 Mar 2025	Odometer:				Oil level	~		
VIN: VI Note: This repo This report is a diagnostic testir		Novt Comico							
This report is a diagnostic testir		Next Service:	165000	Service History	/: No	Smoke & fumes	~		
This report is a diagnostic testir						Performance	~		
diagnostic testir	ort is not a warranty		f		hann diamanala da an	Noise	~		
البابية معاليتهم	ing undertaken. The v	ehicle has been	driven up to 50km	n/h from cold. The \	endor recommends	Cooling System	•		<u> </u>
a fuil mechanica	al inspection prior to	purchase and th	nis can be arranged	for an additional c	harge.	Coolant condition	~		1
						Performance	~		
Key:	s sc	-0	S SC S SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			The second se	Transmission	•		
D = dent					S SC	Operation	~		
R = rust PT = paint defect					THA	Noise	~		
C = crack				$+ \mathbf{\nabla}$	S SC	Clutch	•		~
P = pin dent					<u>л</u> ш	CV joints	~		-
* = decals	sc 916				ELLE SSC	Wheel bearings	v		
SC = stone chips	~	V A		La	&	Brakes	•		
W = significant so	scuffs S	$- \emptyset$	SSC SDP	sc V	SC	Performance	~		
		Note: som			layed in the diagram	Hand Brake	~		──
	ection Comments			les may not be disp	ayed in the diagram		•	ofture))
Headlights faded. Windscreen has cracks. Dent by Ih door						Tyres (lowest observed tread depth of tyres) Left front 6.5			
								.5	mm
						Right front		.0	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear			
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	oot split and leaking g			acwarn Carpontin	a bolt bas cracks	Suspension			
	voir appears to be lea			ies worn. serpentin	e Delt has clacks.	Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Cor	mments					Operation	~		
	Average					Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboard	d Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Conoral C	mmorte					Window winder FR		~	<u> </u>
General Comments Drivers window n/w					Window winder RL	~		Ļ	
Divers wind0	J vv 11/ VV					Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
÷	ing Mechanism:	Cambelt				Sat. Nav. (basic test only)			~
I Evidence of	f Cam Belt Replace	ement: N	0	Kms:		Reversing camera			~
Inspected b	by: Reuben Harvey					Date: 05 Apr 202			

Name: