

Report ID: 25,677,318


Version: 1

Created: 04 Apr 2024

| Make: | Land Rover | Model: | Range Rover | Body Style: | SUV |
|-------------|-------------------|---------------|-------------|----------------|-------------|
| Year: | 2014 | Registration: | PBJ284 | Reg Expiry: | 12 Jun 2024 |
| WoF Expiry: | 13 Jun 2024 | Odometer: | 138,565 Kms | Good No: | 25677318 |
| VIN: | SALGA2KE9EA148772 | Next Service: | 141,000kms | Service Histor | y: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Paint cracked on bumpers.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front differential oil leak.

| <u>Interior Comments</u> | | | | |
|--------------------------|------------------------------------------|--|--|--|
| Seats | L/R seat ripped, R/F seat pocket ripped. | | | |
| Carpets | Average | | | |
| Panels | Cargo blind / tray missing. | | | |
| Dashboard | Average | | | |

General Comments

AWD diesel auto SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Kms.

| Evidence of Carri Bert Replacement. 140 | 11113. | Reversing camera | | |
|--------------------------------------------------|--------|------------------|-----|--|
| Inspected by: Daryll Timms | | Date: 04 Apr 2 | 024 | |
| I have read and understood this condition guide. | Name: | Signature: | | |

| | Pass | Fail | N/A |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | - | I . | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 4 | 4 | mm |
| Right front | | 5 | mm |
| Left rear | 5 | | mm |
| Right rear | - | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | - |
| Operation | ~ | | |
| Electrical / Accessories | l | | 1 |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | \(\times \) \(\t | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | ~ | | |
| Reversing camera | ~ | | |
| g carriera | | | |
| D . 04 4 30 | | | |