

SAFETY INSPECTION

Vehicle Inspection New Zealand Limited

Head Office: P.O. Box 14-149, Panmure, Auckland 1741.

Note: This checksheet does not constitute a Warrant or Certificate of Fitness

CUSTOMER COPY

1938538

NB: This is NOT a
Pre-Purchase Inspection

WOF / COF
(circle)

Plate: WS2481 ✓
1997 HINO FY 1KULA

Current Expiry: 08/07/2016
TYPE/YELLOW

Insp grp: 22 06 mth:
1st NZ Reg: 08/12/199'

Registered Person:

Class: NC GOODS VEHICLE GVM

Fuel: DIESEL

VIN Location: RH STEP

No of Axles: 4 ✓

Odo Reading: 737799 (K)

Hubo Reading: 127053

Last Inspection: PASSED ✓

Last Hubo Serial No: 384035

Certs: HVET (01/06/2023)

HVEA (19/10/2021)

Front Test Wgt: 3240 /3240

HVEC

Rear Test Wgt: 4350 /4350

TSL #	
AVIC #	UP
Invoice #	05-96682
Amount \$	
Payment type	AC-CS-CQ-EFT-cc
Brake recheck fee \$	
Checklist	HE
Revision	

(Details available on request)

Name:

Address:

If different from above.

For reminder.

Please send me a reminder electronically of when my next Wof/CoF inspection is due by text to: _____ and / or email to: _____

VIN / chassis number

JTHA711KULX>X>X10082

Lane:	Initial Inspection	Lane:	Recheck Inspection
Hubodometer serial number:	Odometer: 737799 Hubodometer: 127246	Odometer:	Hubodometer:

Certifications: 5413 5444 5446
5450 5451 5467 HV Brake
SRT Other LVV

Axle	Tyre tread mm		Service brakes			Park brake		Service brakes			Park brake	
	Left	Right	Left	Right	Imbalance	Left	Right	Left	Right	Imbalance	Left	Right
1	7	7	1360	1446	679							
2	10	3	1094	852	26/84	476	797					
3	9/9	12/12	1524	1100	39/61	1988	1496					
4	12/12	14/14	19034	15474	183							
5												
Brakes - Whole Vehicle			16	%	36	Park brake or static			%		Park brake or static	
Brake performance may be recorded as % for each axle or as individual wheel brake force values												

Air system checks	
Max pressure	5.9
Appl's / Pressure	5.0
LPWD activation pressure	3.2
Recovery time	80
Protection-Auxiliary	☐ P ☐ F
Isolation	☐ P ☐ F
Tractor Protection	☐ P ☐ F

Abbreviations: ☐ P = Pass, ☐ F = Fail Explanation of result: ☐ P ☒ F item has passed, ☐ P ☐ F item has failed, ☐ P ☐ F item is not applicable to this vehicle.

Pass / Fail	Inspector ID
Vehicle exterior	☐ P ☒ F
Vehicle structure	☐ P ☒ F
Under Bonnet	☐ P ☒ F
Lighting	☐ P ☒ F
Vision & Glazing	☐ P ☒ F
Vehicle interior	☐ P ☒ F
Brake Systems	☐ P ☒ F
Steering & suspension	☐ P ☒ F
Underbody	☐ P ☒ F
Tyres & wheels	☐ P ☒ F
Motive & Exhaust	☐ P ☒ F
Towing connections	☐ P ☒ F

Fault Codes

REASONS WHY THE VEHICLE WAS FAILED

1. Evaluate 3rd and 4th axle service brakes
2. Treat rust on 1st chassis cross members
3. Rust on cab roof
4. Moisture in LH head lamp.

FOR YOUR INFORMATION ONLY

NAME: SURGE
Rust underbody
for repairs / flow

Rechecks must take place within 28 days of the original inspection. After this time a new inspection must be carried out and a new fee paid. A fee may apply to heavy vehicle rechecks. Complaints regarding Certificate / Warrant of Fitness issues should be first directed to the issuer.

NZ Transport Agency reserves the right to recheck any vehicle following an inspection.

Inspection date: 21.12.17

PASS / FAIL

Recheck date:

PASS / FAIL

New expiry date:

